

Refresher Training: Packing and Shipping Category A Samples

State Hygienic Laboratory at the University of Iowa November 2024


Category A Packaging Instructions

Triple pack all specimens in:

- 1. Leakproof primary receptacle; multiple primary receptacles should be individually wrapped or separated (plates, blood tubes, swabs).
 - 1. The lids of tubs, swabs, plates, etc. must be wrapped with parafilm to prevent accidental opening during transport.
 - 2. Leakproof secondary receptacle, (example: specimen bag).
 - 3. Rigid outer packaging
- If specimen is a liquid, place enough absorbent material between the primary and secondary receptacle to soak up the contents in case of a spill.
- Place a list of contents and paperwork between the secondary receptacle and outer packaging.



Category A Packaging





Outer Packaging Labels

- Label outer packaging with:
 - Infectious substance (diamond shaped label)
 - UN2814 INFECTIOUS SUBSTANCE, AFFECTING HUMANS ANCE CASE OF DAMAGE OR I FAM IMMEDIATELY NOTIFY PUBLIC HEALTH AUTHORIT 6 INF9835


٠

Proper shipping name and UN 2814 certification mark



Outer Packaging Labels

Shipper and consignee identification (name, ٠ address, and telephone)



Package orientation arrows if primary receptacle exceeds 50 ٠ mL or more






24/7

24/7 Emergency Contact Information

The 24/7 emergency contact must be someone with knowledge of the sample being transported and the associated hazards.

They must also be available to answer the phone for the duration of the time that the package is in transit.






Overpack

- An overpack is used for additional protection when shipping sensitive materials.
- It can also be used if the package sent is not large enough to hold all the labeling required for shipping.
- If using an overpack all labels placed in the original container must be placed in the overpack container with the addition of an overpack label. (see next slide)







Shipper's Declaration

A shipper's declaration is required when shipping category A specimens.

A blank template can be found here:

https://www.iata.org/contenta ssets/a9f496cd8c87466b981 42fa6d4cdb209/shippersdeclaration-column-formatfillable.pdf

Note: If sending the package via the SHL courier, an Air Waybill No. is not applicable.

SHIPPER'S DECLARATION FOR DANGEROUS GOODS

Obligger					
Shipper Institut ABC 78 rue Longue 1000 Bruxelles		Air Waybill No. Page 1 of 1 Pages Shipper's Reference Number			
Belgium	(optional)				
Consignee Company XYZ	0		For optiona for		
456 Main Street Montreal QC H32 2Y7 Canada	Company logo name and address				
Two completed and signed copies of be handed to the operator.	of this Declaration must	WARNING			
TRANSPORT DETAILS			omply in all respe		
This shipment is within the limitations prescribed for: (delete non-applicable) PASSENGER GARCIAL AND CARGER ALCRAET		Dangerous Goods Regulations may be in breach of the applicable law, subject to legal penalties.			
AND CARGO AIRCRAFT					
Airport of Destination:	Montreal	Shipment type: (delete non-applicable) NON-RADIOACTIVE R&XXXE			
NATURE AND QUANTITY OF DA	NGEROUS GOODS				
Dangerous Good	s Identification	1		: :	
UN I or I Proper Shipping N ID I No.	I Class I P or Division (Subsidiary G Risk)	ing typ	luantity and ie of packing	Packing I Inst.	Authorization
UN2814 Infectious substance, a I humans (Bacillus anthr I		20 ml			
UN1845 Dry ice		i5kg i	die oor filosie ood	1 954 1 1 954 1	
		I All packed in one fiberboard I box I I			
		1		1 1 1 1 1 1	
				<u></u>	
Additional Handling Information					
Emergency contact: Dr Dupont +	32 2 1234567				
I hereby declare that the contr accurately described above by classified, packaged, marked a respects in proper condition international and national gove	y the proper shipping m and labelled/placarded, a for transport according	ame, and are and are in all to applicable	Name/Title of Sign Dr Janssen Jear Place and Date Brussels, 10 Apr	ne	
of the applicable air transport			Signature (see warning above)		

Shippers Declaration

Instructions for how to properly fill out a shipper's declaration can be found in the link below. If an overpack is used, this should be stated in the shipper's declaration.

https://www.cdc.gov/orr/ipp/docs/guidance_for_shippers_ declaration_508.pdf

The Shipper's declaration must be placed on the outside of the package. At least 2-3 copies are required



Shipping label

1330



Training Resources

 Training is required for all employees that perform packaging and shipping of hazardous materials. This refresher training is not meant to take the place of indepth training required by your employer.

Available on-demand online training:

https://reach.cdc.gov/course/packing-and-shippingdangerous-goods-what-laboratory-staff-must-know





Questions?

Andrea Morris, MPH Biothreat Coordinator/ Biosafety Officer State Hygienic Laboratory

Office: 319-467-4867 Cell: 817-681-1512 Email: andreac-morris@uiowa.edu

